

GOVERNMENT OF TELANGANA  
ROADS & BUILDINGS DEPARTMENT

From,  
Sri. V Sravan Prakash, B.Tech,  
District R&B Officer,  
Ranga Reddy District,  
Goshamahal, Hyderabad-12.

To,  
The Chairman,  
Delhi Public School,  
Nadergul(v), Badangpet(M),  
Hyderabad - 501510.

Lr. No. EE(R&B)/RRD/DB/HD/D3/2022-23/474

Dt:14.06.2022

Sir,

Sub - (R&B) Department - Delhi Public School, Nadergul(v), Badangpet(m),  
Ranga Reddy District - Structural Soundness Certificate - Issue -  
Regarding

Ref - 1. Chairman, Delhi School of Excellence, Nadergul (v), Lr. No. Nil,  
Dt: 30.04.2022  
2. DEE(R&B), Shamshabad Sub-Division Lr. No. DEE/SHBD/Building/  
Soundness/2022-23/29/1, Dt: 13.05.2022  
....

With reference to your letter 1<sup>st</sup> cited, it is to inform that the Deputy Executive Engineer (R&B), Shamshabad Sub-Division has informed that they have inspected the the above building and stated that the building is constructed with Stilt+ Ground+ 4 Floors and the building belongs to M/s Balajee Arun Educational society as per records.

Further, it is to inform that as per Municipal corporation office records the building permission was accorded on 11.04.2018 upto 3 Floors and permission for fourth floor was obtained on 25.08.2020, the building construction completed in the year 2020-21. There are no structural drawings submitted along with application or during inspection due to which only superficial inspection of the building was done.

During inspection following observation are made as detailed below:

1. The building constructed with stilt + Ground + 4 Floors.
2. Marble Flooring done in the Ground + 4 Floors.
3. Painting was done last two year back.
4. No Dampness in the External and Internal walls and Roof slabs.
5. In terrace floor, impervious coat layer has damaged at several locations, these are needed to be rectified.
6. In terrace floor, column reinforcement is exposed and getting rusty with weather. Dummy Columns Concrete to be laid.

Further, you have submitted structural soundness certificate obtained from Licensed Engineer i.e., S.G.S Murthy, Vaaraja Associates, Himayathnagar wherein it is stated that building is structurally safe and soundness and followed the relevant IS code standards and NBC 2005 during construction.



(PTO)

In view of the above, it is to inform that based on report from S G S Murthy, Varja Constructions, the building structural sound & fit for running school for a period of year. However, the school management is completely responsible for taking periodical maintenance of the building regularly during this one year period.

Yours faithfully,

  
District R&B Officer,  
Ranga Reddy District

2/16  
Copy to Dy. Executive Engineer, Shamshabad Sub Division, Hyderabad for information.

